

RHIC/AGS maintenance and start-up schedule

2/23/2000
Thomas Roser

	Cryostats closed												Today	Shield walls up																																							
	3-Jan	10-Jan	17-Jan	24-Jan	31-Jan	7-Feb	14-Feb	21-Feb	28-Feb	6-Mar	13-Mar	20-Mar	27-Mar	3-Apr	10-Apr	17-Apr	24-Apr																																				
RHIC	blue and yellow w		dry run		dry run				p.s. tests		p.s. tests/beam tests		beam tests																																								
Booster/AGS	high intensity protons for g-		p-Au-p		protons for g-2												Au for RHIC																																				
PASS	ODH	rf rad. recert.		ODH	rad. recert.																																																
RF			testing				testing																																														
Power supplies	p.s. start-up and testing												switch to ring																																								
	150 A bipolar p. s. - install and test in 1010 and 1006												remaining 150 A and 300 A bipolar p. s. - procure and install																																								
	50 A corrector power supplies mod./repair/test																																																				
Cryogenics					Cool-down to 50K		B to 4K		Y to 4K																																												
Mechanical	scraper installation						polarim. install. - sect. 12 b																																														
Facility	Installation of fence around RHIC																																																				
Controls																																																					
Booster/Preinj.																																																					
AGS																																																					
	3-Jan	10-Jan	17-Jan	24-Jan	31-Jan	7-Feb	14-Feb	21-Feb	28-Feb	6-Mar	13-Mar	20-Mar	27-Mar	blue cold												yellow cold																											